Н

a)


b)

Crowell & Moring LLP Customer Service No. 23911


BEST AVAILABLE COPY

Fig.2

c)




Crowell & Moring LLP Customer Service No. 23911 P609816 Attorney Docket No. 420FR/50819 Filed: January 16, 2002 Sheet 2 of 4 BEST AVAILABLE COPY 11 <u>10</u> -90° Ausgang + 13 Fig.4 NPUT Eingang 22 λ/4 <u>20</u> a) 21 -90° 23 24



IIII HEELE II II II E

Attorney Docket No. 420FR/50819 Filed: January 16, 2002 Sheet 3 of 4






Fig.6

Attorney Docket No. 420FR/50819 Filed: January 16, 2002 Sheet 4 of 4

